

50Hz 1450 rpm

$H (m)$

200

100

90

80

70

60

50

40

30

20

10

10

20

30

40

50

60

70

80

90

100

200

300

400

500

600

700

800

900

1000

2000


3000

4000

5000

10000

$Q (m^3/h)$



60Hz 1750 rpm

$H$  (M)

